Application/Control Number: 09/749,370

Art Unit: 2833

None of prior art teaches or suggest the apparatus further comprising the first guide pin is threaded on the first bolt; and the second guide pin is threaded on the second bolt; wherein the

Page 8

first guide pin and the second guide pin secure the mounting plate to the first bolt and the second

bolt, and combination of all the claim above.

12. Wu et al (US6007360) is cited to show the guide socket having end member 4 including a

thread engaging to thread inside the screw 41.

Conclusion

13. Any inquiry concerning this communication or earlier communications from the

examiner should be directed to Phuongchi T Nguyen whose telephone number is (703) 305-

0729. The examiner can normally be reached on Monday through Thursday from 8:00AM to

4:30PM.

If attempts to reach the examiner by telephone are unsuccessful, the examiner's

supervisor, Paula Bradley can be reached on (703) 308-2319. The fax phone numbers for the

organization where this application or proceeding is assigned are (703) 305-7723 for regular

communications and (703) 305-7723 for After Final communications.

Any inquiry of a general nature or relating to the status of this application or proceeding

should be directed to the receptionist whose telephone number is (703) 308-7722.

May 6, 2001

Gary Paumen

Primary Evaminer